

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846		2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718		4. Manifest Tracking Number 007511116 FLE		
		5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 Generator's Phone: (318) 269-7400		Generator's Site Address (if different than mailing address) SAME					
6. Transporter 1 Company Name Clean Harbors		U.S. EPA ID Number AK007102201							
7. Transporter 2 Company Name		U.S. EPA ID Number							
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40385 S County Road 236 Wavoka, OK 73860 Facility's Phone: (580) 697-3500		U.S. EPA ID Number OKD065438376							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) 1HA3077 HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III			10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
									F001 F002 F003 F004 F005
14. Special Handling Instructions and Additional Information 1. CH831502X08 EPG#171									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Officer's Printed/Typed Name John T. Hume					Signature <i>[Signature]</i>		Month Day Year 12 3 14		
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: _____ Date leaving U.S.: _____						
	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name John T. Hume					Signature <i>[Signature]</i>		Month Day Year 12 3 14	
	Transporter 2 Printed/Typed Name					Signature		Month Day Year	
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	18b. Alternate Facility (or Generator) Manifest Reference Number: _____ U.S. EPA ID Number _____								
	Facility's Phone: _____								
	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H132		2.		3.		4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name					Signature		Month Day Year		

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846		2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718		4. Manifest Tracking Number 007511116 FLE		
		5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400				Generator's Site Address (if different than mailing address) SAME			
6. Transporter 1 Company Name CLEAN HARBORS							U.S. EPA ID Number MA003732250		
7. Transporter 2 Company Name							U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wynoka, OK 73860 (580) 697-3500							U.S. EPA ID Number OKD065438376		
Facility's Phone:									
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
					No.	Type			
	x	1. HA3077. HAZARDOUS WASTE, SOLID, H.O.S., (F001, F003), 9. PG III			1	DT	EST 140	Y	F001 F002 F003 F004 F005
		2.							
		3.							
	4.								
14. Special Handling Instructions and Additional Information 1. CH831502X08 ERG#171 TR# 1600 TL# US9.5T									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offoror's Printed/Typed Name Jim Tyson					Signature <i>Jim Tyson</i>		Month Day Year 12 4 14		
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____								
	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name Jeff Higgins				Signature <i>Jeff Higgins</i>		Month Day Year 12 4 14		
	Transporter 2 Printed/Typed Name				Signature		Month Day Year		
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	Manifest Reference Number: _____								
	18b. Alternate Facility (or Generator) U.S. EPA ID Number								
	Facility's Phone: _____								
	18c. Signature of Alternate Facility (or Generator) Month Day Year								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
	1. H132		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name David Hays					Signature <i>David Hays</i>		Month Day Year 12 4 14		